


Disassembly bild s.77

(Stand: 04.10.21)

	method	size	quantity
●	screw	T20	22
●	headless screw	SW4	1




Disassembly bild s.77

(Stand: 04.10.21)

	method	size	quantity
●	screw	T10	4
●	screw	T20	2
●	screw	PH2	9

LOEWE.




Disassembly bild s.77

(Stand: 04.10.21)

	method	size	quantity
	screw	T10	6
	screw	PH1	2
	screw	T15	2
	headless screw	SW 2	1


gear unit



Disassembly bild s.77

(Stand: 04.10.21)

	method	size	quantity
	screw	T10	7
	screw	T20	15
	screw	T15	4



Disassembly bild s.77

(Stand: 04.10.21)

	method	size	quantity
	screw	T6	2
	screw	T20	10

